

EMPLOYEE INFORMATION/QUALIFICATION RECORDS



 	Name	Chris Brocato		DOB		
	Classification	Owner/Operator		ID#	2351	
	Address	1847 Brewer Rd		City	Batesville	
	County	Panola	State	MS	Zip	38606
	Natural Gas Department					
	All training and evaluations are based on the ASME B310 amendment of the Final Rule.					

TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	1/08/15	1/08/15
02	Purging of Natural Gas	1/08/15	1/08/15	17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: 8" Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	1/08/15	1/08/15	18	Installing Gas Meters	1/08/15	1/08/15
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	1/08/15	1/08/15
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	1/08/15	1/08/15
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	1/08/15	1/08/15	25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	1/08/15	1/08/15	26	Abandonment / Deactivation of Gas Facilities	1/08/15	1/08/15
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	1/08/15	1/08/15	28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey



Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
 		Name	Steve Towns		DOB		
		Classification	Contractor		ID#	4930	
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
All training and evaluations are based on the ASME B310 amendment of the Final Rule.							
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	1/08/15	1/08/15
02	Purging of Natural Gas	1/08/15	1/08/15	17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: 8" Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	1/08/15	1/08/15	18	Installing Gas Meters	1/08/15	1/08/15
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	1/08/15	1/08/15
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	1/08/15	1/08/15
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	1/08/15	1/08/15	25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	1/08/15	1/08/15	26	Abandonment / Deactivation of Gas Facilities	1/08/15	1/08/15
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	1/08/15	1/08/15	28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey



Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	Michael Harper		DOB		
		Classification	Contractor		ID#	8898	
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	1/08/15	1/08/15
02	Purging of Natural Gas	1/08/15	1/08/15	17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: 8" Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	1/08/15	1/08/15	18	Installing Gas Meters	1/08/15	1/08/15
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	1/08/15	1/08/15
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	1/08/15	1/08/15
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	1/08/15	1/08/15	25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	1/08/15	1/08/15	26	Abandonment / Deactivation of Gas Facilities	1/08/15	1/08/15
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	1/08/15	1/08/15	28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey



Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	Richard Drewrey		DOB		
		Classification	Contractor		ID#		
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	No Participation	
02	Purging of Natural Gas	No Participation		17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	No Participation		18	Installing Gas Meters	No Participation	
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	No Participation	
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	No Participation	
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	No Participation		25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	No Participation		26	Abandonment / Deactivation of Gas Facilities	No Participation	
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	No Participation		28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey


Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	Dustin Dunn		DOB		
		Classification	Contractor		ID#		
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	No Participation	
02	Purging of Natural Gas	No Participation		17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	No Participation		18	Installing Gas Meters	No Participation	
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	No Participation	
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	No Participation	
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	No Participation		25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	No Participation		26	Abandonment / Deactivation of Gas Facilities	No Participation	
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	No Participation		28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey



Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	Joe Herrin		DOB		
		Classification	Contractor		ID#		
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	No Participation	
02	Purging of Natural Gas	No Participation		17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	No Participation		18	Installing Gas Meters	No Participation	
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	No Participation	
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	No Participation	
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	No Participation		25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	No Participation		26	Abandonment / Deactivation of Gas Facilities	No Participation	
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	No Participation		28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey



Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	William Ivy		DOB		
		Classification	Contractor		ID#		
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	No Participation	
02	Purging of Natural Gas	No Participation		17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	No Participation		18	Installing Gas Meters	No Participation	
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	No Participation	
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	No Participation	
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	No Participation		25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	No Participation		26	Abandonment / Deactivation of Gas Facilities	No Participation	
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	No Participation		28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey

Field Test Evaluator : Michael Lindsey

EMPLOYEE INFORMATION/QUALIFICATION RECORDS							
		Name	Paul H Fowler		DOB		
		Classification	Contractor		ID#		
		Address	1847 Brewer Rd		City	Batesville	
		County	Panola	State	MS	Zip	38606
		Natural Gas Department					
		All training and evaluations are based on the ASME B310 amendment of the Final Rule.					
TT	Covered Task Name	Tested	Field Evaluation	TT	Covered Task Name	Tested	Field Evaluation
01	Odorant and Odorization	No Participation		16	Maintaining and Repairing of PE Piping	No Participation	
02	Purging of Natural Gas	No Participation		17	Plastic Pipe Fusion and Inspection of Joints	1/08/15	
03	Cathodic Protection	No Participation			(0751) Size: Butt Fusion		1/12/16
04	Atmospheric Corrosion	No Participation			(0781) Electrofusion		1/12/16
05	Operating and Maintaining Primary Gas Valves	No Participation		18	Installing Gas Meters	No Participation	
06	Inspecting Pressure Regulating/Limiting Stations	No Participation		19	Tapping and Stopping	No Participation	
07	Pressure Testing To Establish Gas Service	No Participation		20	Backfilling / Excavating	No Participation	
08	Leak Investigation and Odor Complaints	No Participation		21	Pigging	No Participation	
09	Walking/Mobile Leak Survey	No Participation		22	Boring	No Participation	
10	Patrolling	No Participation		23	Welding on Gas Pipelines	No Participation	
11	Locating and Marking Pipeline Facilities	No Participation		24	Control Room Management	No Participation	
12	Maintaining and Repairing of Steel Piping	No Participation		25	Sensing Device	No Participation	
13	Maintaining and Repairing of Cast Iron Piping	No Participation		26	Abandonment / Deactivation of Gas Facilities	No Participation	
14	Installation of Pipe Above Ground	No Participation		27	Prevention Accidental Ignition	No Participation	
15	Field Repair Pipe Coating	No Participation		28	System Upgrading	No Participation	

These documents are the property of Tri-State Meter & Regulator Service. Any reproduction of these documents without written consent is prohibited.

Written Test Evaluator : Michael Lindsey

Field Test Evaluator : Michael Lindsey